

PLANNING/DESIGN

Valued at \$580.6M March 2025

1 Ajayan Bridge Replacement Status: Design Completed Estimated Construction Cost: TBD Designer: NC Macario & Associates Estimated start of construction: TBD

2 Aplacho Bridge Replacement
Status: Design Completed
Estimated Construction Cost: TBD
Designer: Duenas Camacho & Associates
Estimated start of construction: TBD

Route 10A, Phase 1 Reconstruction and Widening , GIA/Tiyan Intersection
Status: Design In Progress

Estimated Construction Cost: \$25M Designer: Duenas Camacho & Associates Estimated start of construction: FY2026

Route 14B, Ypao Road, Phase 2
Status: Design Completed
Estimated Construction Cost: 12.6M
Designer: EM Chen & Associates
Estimated start of construction: FY2026

5 Route 17, Phase 2B Status: Design Completed Estimated Construction Cost: \$48M Designer: Duenas, Camacho & Associates Estimated start of Construction: FY2026

6 Route 20 (Tiyan Parkway), Phase 2 Status: Design Completed Estimated Construction Cost: \$31.4M Designer: TG Engineers Estimated start of construction: TRD

Route 20 Tiyan Parkway Structure Demolition, Phase 2

Status: Planning Estimated Construction Cost: \$750,000 Designer: TBD

Estimated start of construction: FY2026

Route 1/8 Memorial

Status: Planning
Estimated Construction Cost: TBD
Designer: TBD
Estimated start of construction: TBD

Route 10 Safety Improvements
 Status: Design Completed
 Estimated Construction Cost: TBD
 Designer: WSP USA, Inc.
 Estimated start of construction: FY2025

10 Ylig Memorial
Status: Design Completed
Estimated Construction Cost: \$500,000
Designer: PTG
Estimated start of construction: FY2025


Route 1 Pavement Markings Restoration, Juan Jacinto Drive to Gayinero Road (Maintenance)
Status: Planning in Progress
Estimated Construction Cost: TBD
Designer: NA
Estimated start of construction: TBD

Poute 8 Pavement Markings Restoration, Route 1 to Tri-Intersection (Maintenance)
Status: Planning in Progress

Estimated Construction Cost: \$354,000 Designer: NA Estimated start of construction: TBD

Route 4 Pavement Markings Restoration, Route 1 to Pago Bay Bridge (Maintenance)

Status: Planning in Progress
Estimated Construction Cost: TBD
Designer: NA
Estimated start of construction: TBD



Islandwide Raised Medians Painting, Route 1
(Route 8 to Macy's Entrance), Route 16 (Route 1 to
Tri-Intersection), Route 4 (Route 10 to Route 1),
Route 8 (Route 1 to Tri-Intersection) Maintenance
Status: Planning in Progress
Estimated Construction Cost: \$46,000

Estimated Construction Cost: \$46,000 Designer: NA Estimated start of construction: TBD

15 Islandwide Accessibility Accomodation and Drainage Improvements

Status: Completed
Estimated Construction Cost: \$500,000
Designer: WSP USA, Inc.
Estimated start of construction: FY2025

Leo Palace Bridge / Pago Bridge Scour Countermeasures

Status: Design In Progress Estimated Construction Cost: \$4.6M Designer: GHD Estimated start of construction: FY2026

Fonte Inland, Maina Culvert, & Merizo Inland Culvert Rehabilitation

Status: Design in Progress
Estimated Construction Cost: \$3.7M
Designer: SSFM
Estimated start of construction: 2027


Route 2, 4, and Route 4A Planning Study Status: Planning in Progress Estimated Construction Cost: NA Designer: WSP USA, Inc. Estimated start of construction: NA

Route 1 Reconstruction of Multiple Bridges (Hagatna to Piti)

Status: Design in Progress
Estimated Construction Cost: \$115.5M
Designer: GHD
Estimated start of construction: FY2025

Under Pavement Infrastructure Retrofit Status: Design In Progress

Estimated Construction Cost: \$165.4M Designer: GHD Estimated start of construction: FY2025



(15)

3

37

Status: Design in Progress
Estimated Construction Cost: TBD
Designer: EMPSCO
Estimated start of construction: TBD

Islandwide Bridge Safety Improvements
Status: Design In Progress

Estimated Construction Cost: \$1M Designer: WSP USA, Inc. Estimated start of construction: FY2026

Route 1 Widening at Rt 26, Rt 27, Signal at Liguan Ave - Design

Status: Planning
Estimated Construction Cost: TBD
Designer: TBD
Estimated start of construction: TBD

Route 28 from Route 3 to Bumuchachu Road Status: Planning

Estimated Construction Cost: TBD
Designer: TBD
Estimated start of construction: TBD

Route 10A Reconstruction and Widening, GIAA to Route 16, Phase 2

Status: Design In Progress
Estimated Construction Cost: TBD
Designer: DCA
Estimated start of construction: TBD

Auto Lot Expansion and Shared Access Road Pavement

Status: Design Completed
Estimated Construction Cost: \$705,000
Designer: WSP
Estimated start of construction: TBD

Islandwide Traffic Signal Repairs from Typhoon Mawar

Status: Completed
Estimated Construction Cost: \$2.4M
Designer: TBD
Estimated start of construction: FY2025

28 Islandwide Routed Road Signage Repairs from Typhoon Mawar Damage Status: Completed

Estimated Construction Cost: \$2.4M Designer: TBD Estimated start of construction: FY2025

Route 1 Striping Repairs from Route 6 (Adelup to Alupang Towers) from Typhoon Mawar Damage IDIQ- Task Order

Status: Completed
Estimated Construction Cost: \$800,000
Designer: TBD
Estimated start of construction: FY2025

Guatali Bridge Retrofit

Status: Planning
Estimated Construction Cost: \$15M
Designer: TBD
Estimated start of construction: TBD

Route 15 Widening from Route 10 to GPA/GWA Facility

Status: Planning
Estimated Construction Cost: \$30M
Designer: TBD
Estimated start of construction: TBD

Traffic Signal System Upgrade, Phase 1
Status: Planning

Estimated Construction Cost: \$1.5M Designer: TBD

Estimated start of construction: TBD





33 Traffic Signal System Upgrade, Phase 2

Traffic Signal System Upgrade, I Status: Planning Estimated Construction Cost: \$2M Designer: TBD Estimated start of construction: TBD

34 Route 29 Rehabilitation Status: Planning Estimated Construction Cost: \$30M Designer: TBD

35 Route 27 Widening
Status: Planning
Estimated Construction Cost: \$30M
Designer: TBD

Estimated start of construction: TBD

Route 6, Rehabilitation from Rt 1 Veteran
Cemetery to Rt 1 Adelup

Estimated start of construction: TBD

Status: Planning
Estimated Construction Cost: \$25M
Designer: TBD
Estimated start of construction: TBD

Route 26 Widening
Status: Planning
Estimated Construction Cost: \$17.6M

Designer: TBD
Estimated start of construction: TBD

Islandwide Safety Projects
Status: Design In Progress
Estimated Construction Cost: \$7.5M

Designer: TBD
Estimated start of construction: FY2024-FY2027

39 Islandwide Pavement Improvements (Pavement and Pavement Marking) (IDIQ): TO 3 Route 2A, 8, 14A, 30, 32

Status: Design In Progress
Estimated Construction Cost: \$1.5M
Designer: WSP
Estimated start of construction: FY2025

40 Islandwide Pavement Improvements (Pavement and Pavement Marking) (IDIQ): TO 5 Route 1, Asan

Status: Design In Progress
Estimated Construction Cost: \$1.9M
Designer: WSP
Estimated start of construction: FY2026

41 Islandwide Safety Improvements (Striping and Marking) (IDIQ): TO 1 Route 1, Route 11 to Route 6

Status: Design In Progress Estimated Construction Cost: \$1.5M Designer: WSP Estimated start of construction: FY2025

42 Islandwide Safety Improvements (Striping and Marking) (IDIQ): TO 3 Route 1, Route 27 to AAFB

Status: Design In Progress
Estimated Construction Cost: \$2.3M
Designer: WSP
Estimated start of construction: FY2025

RR Cruz Drainage Improvements
Status: Design In Progress
Fetimated Construction Cost: TRD

Estimated Construction Cost: TBD
Designer: WSP
Estimated start of construction: FY2026

Tiyan Access Road
Status: Design In Progress
Estimated Construction Cost: TBD
Designer: DCA
Estimated start of construction: FY2025

